



Case Study

Water Damage Restoration for a Commercial Building

San Diego, CA



San Diego, CA

Water Damage Restoration

A busted four-inch chilled-water supply line caused massive flooding at the headquarters of a semiconductor and telecommunications equipment company in San Diego, CA. The basement, lobby, corridors, common areas and more than 60 office spaces through the sixth floor were affected by the water damage.

Because of the size and severity of the loss, the company reached beyond its long-term exclusive relationship with an ATI competitor to seek bids for the work the same day. ATI, which inspected the site and submitted its proposal within hours, was awarded the mitigation project that night.

ATI crews worked after standard office hours and weekends, as well as around occupied workspaces, to limit business interruption for the client. The location of the building's soffit vents 60 feet above a lobby atrium required workers to be specially harnessed as a safety precaution.

Despite the many challenges, ATI completed the project on time to the great satisfaction of the client.





About ATI RESTORATION, LLC

Established in 1989 by Gary Moore, ATI Restoration, LLC, is the nation's largest family-operated restoration contractor. Headquartered in Anaheim, California, the company specializes in restoration, environmental and reconstruction services following natural and man-made disasters with an unwavering commitment to customer service. To learn more, visit ATIrestoration.com or call (800) 400-9353.



(800) 400-9353

www.ATIrestoration.com

©2020 ATI. All Rights Reserved.