



Case Study

Water Damage Restoration for a Commercial Building

Santa Ana, CA



Santa Ana, CA

Water Damage Restoration

Water leakage on the ninth floor of a commercial building in Southern California led to major water loss. The water affected all restrooms and common areas not only on the floor it started, but also on the eight floors beneath.

ATI immediately began water extraction. Commercial drying equipment was set up throughout the building to reduce the humidity and prevent secondary damages on all surfaces. Drywall, ceilings and floors were the priorities.

Because most of the walls were wallpapered, it was a very labor-intensive project. Wallpaper was removed along with the drywall. Once moisture assessments cleared the area of mold, drywall was replaced, retextured and the walls re-wallpapered.

Offices in the building sustained little or no damage, so they could stay open for business. ATI crews worked in the evenings to complete the project so that the businesses were not disrupted, and tenants were extremely happy with the results.





About ATI Restoration, LLC

Established in 1989 by Gary Moore, ATI Restoration, LLC, is the nation's largest family-operated restoration contractor. Headquartered in Anaheim, California, the company specializes in restoration, environmental and reconstruction services following natural and man-made disasters with an unwavering commitment to customer service. To learn more, visit ATIrestoration.com or call (800) 400-9353.



(800) 400-9353

www.ATIrestoration.com

©2020 ATI. All Rights Reserved.